## INSPECTION REPORT REVIEW POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : SOONER DIAL COMPANY LOCATION : CLINTON SITE NUMBER: OKD987096591 SURVEY DATE:/_/ INSPECTED BY: STATE FIT TAT OTHER: LABORATORY :CLPEPAOTHER
RECEIVED FROM: DATE RECEIVED: _5   26   93
SAMPLE TYPE(s):
SOIL SURFACE WATER GROUND WATER DRINKING WATER off / on -site off / on -site off / on -site
CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological
FOLLOW UP (Y/N):  (Re) Sampling Requested Further Action is URGENT    Locate Drinking Water Sources   Keep Site Active ("N"=No Further Action)   Concur with Report Recommendations
Site Evaluation accomplished. No faither action.  Site Evaluation accomplished. No faither action.  64-58 concert.  Vish to divinleing water supplies is min, mod.
Concurrence: Mark & McCalland 5,26,193 ENGINEER/REVIEWER  F. Wowen Nowis 5, 26,93